

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/4/2012 STORM: Sandy PARTY: CAS/KAC

SITE INFORMATION

SITE NAME: HWM-NJ-MON-212 LATITUDE (DD to 6 places): 40.42251
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 2 Benton Ave LONGITUDE (DD to 6 places): 74.05932

STATE: NJ COUNTY: Monmouth Landowner notified (circle one): (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other _____

Type of mark: debris line, mud line, seed line, wash line, other _____

Mark location (circle one): Inside (Outside) Approx. height above ground (ft): 0.38

Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: mudline on door to northwest ^{door} entrance to porch
of residence at 2 Benton Ave. Stairs to ^{north end of} porch are ~20ft to Beach Ave.
Marked w/ ^{HWM} ~~Survey~~ marker to left of door.

HWM Elevation: 11.295
11.309 > 11.332 + 0.38 = (11.712 ft)

RM Description: _____

RM #: _____ RM Elevation: _____

Other Notes: _____

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No Camera Owner: CAS

Digital Photo Filenames: _____


Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____



Additional Notes:
